

**Vehicle Description**

DATE INSPECTED: 20/02/2020

Mitsubishi Triton MN GLX Utility Double Cab 4dr Man 5sp 4x4 2.5DT

VIN MMAJNKB40FD028744  
Compliance Date 03/2015  
Build Date 2015  
Odometer Reading 197347  
Registration Number UNREG  
Registration Expiry  
Last Serviced See Dealer



**Overall Rating**

Note: 5 Star ratings are usually reserved to near new and ex-factory driven demonstrator vehicles



Seats

4.0 - GOOD



Suspension

4.0 - GOOD



Lights

5.0 - VERY GOOD



Brakes

4.0 - GOOD



Engine

4.0 - GOOD



Body & Paint

4.0 - GOOD



Mountings

4.0 - GOOD



Tyres

4.0 - GOOD



Transmission / Gearbox

4.0 - GOOD



Road Test

5.0 - VERY GOOD



Steering

4.0 - GOOD

**NA**  
NOT APPLICABLE

Other



**Seats**

Very minimal wear to seats and trims, in good condition for age/kilometres travelled. Above average for commercial vehicle.



**Lights**

Lights and lenses in good condition and all operational at time of inspection.



**Engine**

Engine/engine bay in good condition at time of inspection, reflecting kilometres and age. No diagnostic fault codes found at time of inspection.



**Mountings**

Mountings are in good condition for age and kilometres.



**Transmission / Gearbox**

Transmission operating well at time of inspection to be expected with kilometres.



**Steering**

Steering components present in well-maintained condition reflecting age and the kilometres on vehicle.



**Suspension**

Suspension and bushes presenting in well-maintained condition.



**Brakes**

Brake pads and discs are in good condition, general wear showing to be expected.



**Body & Paint**

Body and paint presenting in good condition, very minor imperfections to various parts of vehicle to be expected with age and kilometres. Above average for commercial vehicle



**Tyres**

Very minimal wear to tyres



**Road Test**

Vehicle drove and performed well on road test.

**NA**

Other

Overall



General Comments

Overall this vehicle has been rated as '4 STARS' taking into consideration age, kilometres travelled and vehicle use. Vehicle presents in a well maintained condition. Note: all accessories may not have been accessible or tested at time of inspection. Possible minor inclusions and imperfections to be expected with a vehicle of these kilometres, commercial use and age







INSPECT



INSPECT











## Item Ratings

**★★★★★ 5.0 VERY GOOD**

★★★★★ 4.5 Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age & kms of vehicle.

**★★★★☆ 4.0 GOOD**

★★★★☆ 3.5

**★★★☆☆ 3.0 FAIR**

★★★☆☆ 2.5 Item found to be in working order with some signs of damage and/or wear & tear, consistent with age & kms of vehicle.

**★★☆☆☆ 2.0 POOR**

★★☆☆☆ 1.5

**★☆☆☆☆ 1.0 VERY POOR**

★☆☆☆☆ 0.5 Item found not to be in working order and/or major signs of damage and/or wear & tear.

**NA NOT APPLICABLE**

Vehicle does not have this item fitted/installed.

**NC NOT CHECKED**

Potential defect observed but item not further investigated/dismantled.

## RedBook Inspect does not check the following items

- Brake function and lining material, brake drums, limited to what is immediately visible
- Evidence of brake fluid contamination
- Anti-lock braking system (ABS) mechanics
- Meters indicating oil and fuel consumption or the degree of oil and fuel consumption
- Reason for oil leaks
- Oil pump strainer to assess sludge build up
- Wheel cylinders
- Vehicle electrics and electronics
- Transmission mechanics
- Engine cylinder compression
- Engine mountings
- Water pump/fan
- Body water leaks or reason for leaks
- Odometer and camshaft belt, drive belt and timing belt
- Estimated expiry of exhaust system, clutch, dual mass flywheels
- Standard to which repairs or service history have been completed
- Functionality of audio-visual or entertainment system including CD, Cassette, TV, DVD, iPod connectivity, sensors, alarm/security devices, satellite navigation systems/GPS
- Degree of gas emissions
- Catalytic converters
- Additional accessories included as a result of owner's modifications
- Mechanical switching of wipers and lights
- LPG systems
- Air conditioning efficiency
- Status of habitation areas of motorhomes or caravans
- Vehicle's computer systems, such as trip meter computers, cruise control and any other computer systems
- Technical systems

## Disclaimer

- (a) This report is not a warranty.
- (b) The scope of this inspection is visual only and limited to the items checked in the body of the report on the date of inspection, reflecting the age of the vehicle and kilometres travelled on that date. As the inspection is visual only, it does not involve the removal of any parts or components and is therefore limited in scope.
- (c) It is the responsibility of the buyer to check and diligence the vehicle at time of purchase.
- (d) RedBook Inspect assumes no liability or warranty for any defects that may arise subsequent to the date of inspection.
- (e) This report must not be sold or provided to any third party, except with RedBook Inspect's prior written consent.