

## Vehicle Description

Iveco Daily 50C17 3 Seat Turbo Diesel Automatic Truck

DATE INSPECTED: 06/02/2020

ZCFC50C100D478510 VIN 07/2013 **Compliance Date** 

2013 **Build Date** 

107851 **Odometer Reading** Registration Number **UNREG** 

**Registration Expiry** 

01/2020 Last Serviced





## **Overall Rating**

Note: 5 Star ratings are usually reserved to near new and ex-factory driven demonstrator vehicles

Seats Suspension **★★★★** ★ ★ 4.0 - GOOD ★★★★☆ 4.0 - GOOD

**★★★★** 4.0 - GOOD Lights **Brakes** \*\*\*\*

Engine **Body & Paint ★★★☆ ★★★☆** 

Mountings **★★★★☆** 4.0 - GOOD Tyres **★★★☆** 

★★★★☆ 4.0 - GOOD Transmission / Gearbox ★★★★☆ 4.0 - GOOD **Road Test** 

Other Steering **★★★☆** \*\*\*\*





#### Seats

All cloth seats are ok at time of inspection.



### Lights

Lights and lenses in good condition and all operational at time of inspection.



### Engine

Engine/engine bay in good condition at time of inspection, reflecting kilometres and age. No diagnostic fault codes found at time of inspection refer to photo attached.



### Mountings

Visible mounts are in good condition to be expected with kilometres and age.



#### Transmission / Gearbox

Transmission operating well at time of inspection to be expected with kilometres.



### Steering

All steering components are in good condition to be expected with kilometres and age.





### Suspension

All visible steering components in good condition reflecting age and kilometres travelled.



#### **Brakes**

All brake pads are wearing consistent with age and kilometres travelled. All brake discs are ok at time of inspection.



## Body & Paint

Body and paint presenting in good condition. Very minor marks and scratches to various panels of vehicle to be expected with age and kilometres travelled.



### Tyres

All tyres are wearing consistent with age and kilometres travelled.



### **Road Test**

Vehicle drove well and performed well on road test.



Other




## Overall












## **General Comments**

Overall this vehicle has been rated as '4 STARS' taking into consideration age, kilometres travelled and vehicle use. Vehicle presents in a well maintained condition. Note: all accessories may not have been accessible or tested at time of inspection. Possible minor inclusions and imperfections to be expected with a vehicle of these kilometres, age and commercial use

















































#### Item Ratings

★★★★★ 5.0 VERY GOOD

\*\*\*\* 4.5 Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age & kms of vehicle.

★★★☆ 4.0 GOOD

★★★☆☆ 3.5

★★★☆☆ 3.0 FAIR

★★★☆☆ 2.5 Item found to be in working order with some signs of damage and/or wear & tear, consistent with age & kms of vehicle.

★★☆☆ 2.0 POOR

★★☆☆☆ 1.5

★☆☆☆ 1.0 VERY POOR

★☆☆☆☆ 0.5 Item found not to be in working order and/or major signs of damage and/or wear & tear.

**NOT APPLICABLE** NΑ

Vehicle does not have this item fitted/installed.

**NOT CHECKED** NC

Potential defect observed but item not further investigated/dismantled.

#### RedBook Inspect does not check the following items

- Brake function and lining material, brake drums, limited to what is immediately visible
- Evidence of brake fluid contamination
- Anti-lock braking system (ABS) mechanics
- Meters indicating oil and fuel consumption or the degree of oil and fuel consumption
- Reason for oil leaks
- Oil pump strainer to assess sludge build up
- Wheel cylinders
- Vehicle electrics and electronics
- Transmission mechanics
- Engine cylinder compression
- Engine mountings
- Water pump/fan
- Body water leaks or reason for leaks

- Odometer and camshaft belt, drive belt and timing belt
- Estimated expiry of exhaust system, clutch, dual mass flywheels
- Standard to which repairs or service history have been completed
- Functionality of audio-visual or entertainment system including CD, Cassette, TV, DVD, iPod connectivity, sensors, alarm/security devices, satellite navigation systems/GPS
- Degree of gas emissions
- Catalytic converters
- Additional accessories included as a result of owner's modifications
- Mechanical switching of wipers and lights
- LPG systems
- Air conditioning efficiency
- Status of habitation areas of motorhomes or caravans
- Vehicle's computer systems, such as trip meter computers, cruise control and any other computer systems
- Technical systems

#### Disclaimer

- (a) This report is not a warranty.
- (b) The scope of this inspection is visual only and limited to the items checked in the body of the report on the date of inspection, reflecting the age of the vehicle and kilometres travelled on that date. As the inspection is visual only, it does not involve the removal of any parts or components and is therefore
- (c) It is the responsibility of the buyer to check and diligence the vehicle at time of purchase.
- (d) RedBook Inspect assumes no liability or warranty for any defects that may arise subsequent to the date of inspection.
- (e) This report must not be sold or provided to any third party, except with RedBook Inspect's prior written consent.





