

Vehicle Description

DATE INSPECTED: 17/07/2020

145760 Mercedes-Benz Sprinter NCV3 316CDI Van High Roof LWB 4dr 7G-TRONIC 7sp 2.1DT

VIN WDB9066352P406240
Compliance Date 06/2017
Build Date N/A
Odometer Reading 143280
Registration Number UNREG
Registration Expiry
Last Serviced Refer to selling dealer.



Overall Rating

Note: 5 Star ratings are usually reserved to near new and ex-factory driven demonstrator vehicles



3.0 - FAIR

Seats



4.0 - GOOD

Suspension



5.0 - VERY GOOD

Lights



4.0 - GOOD

Brakes



4.0 - GOOD

Engine



4.0 - GOOD

Body & Paint



4.0 - GOOD

Mountings



4.5 - VERY GOOD

Tyres



4.0 - GOOD

Transmission / Gearbox



5.0 - VERY GOOD

Road Test



4.0 - GOOD

Steering

NA

NOT APPLICABLE

Other

**Seats**

Very minimal wear to seats and trims, in good condition for age and kilometres travelled with commercial type use. Attention required to drivers seat adjustment lever.

**Lights**

Lights and lenses in good condition and all operational at time of inspection.

**Engine**

Engine/engine bay is in good/well maintained condition at time of inspection. No diagnostic fault codes found at time of inspection.

**Mountings**

Mountings are in good condition for age and kilometres.

**Transmission / Gearbox**

Transmission selecting gears well and operating as to be expected with kilometres and age of vehicle.

**Steering**

Steering components present in well-maintained condition reflecting age and the kilometres on vehicle.



Suspension

All visible suspension and suspension bushes in good condition reflecting kilometres and age.



Brakes

Brake pads and discs are in good condition, general wear showing to be expected.



Body & Paint

Body and paint in good condition with very minimal superficial imperfections to be expected with age and kilometres travelled with commercial use



Tyres

All tyres recently replaced.



Road Test

Vehicle drove and performed well on road test.

NA

Other

Overall



General Comments

Overall this vehicle has been rated as '4 STARS' taking into consideration age, kilometres travelled and vehicle use. Vehicle presents in a well maintained condition. Note: all accessories may not have been accessible or tested at time of inspection. Possible minor inclusions and imperfections to be expected with a vehicle of these kilometres, age and use.















Item Ratings

★★★★★ 5.0 **VERY GOOD**

★★★★☆ 4.5 Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age & kms of vehicle.

★★★★☆ 4.0 **GOOD**

★★★☆☆ 3.5

★★★☆☆ 3.0 **FAIR**

★★★☆☆ 2.5 Item found to be in working order with some signs of damage and/or wear & tear, consistent with age & kms of vehicle.

★★☆☆☆ 2.0 **POOR**

★★☆☆☆ 1.5

★☆☆☆☆ 1.0 **VERY POOR**

★☆☆☆☆ 0.5 Item found not to be in working order and/or major signs of damage and/or wear & tear.

NA NOT APPLICABLE

Vehicle does not have this item fitted/installed.

NC NOT CHECKED

Potential defect observed but item not further investigated/dismantled.

RedBook Inspect does not check the following items

- Brake function and lining material, brake drums, limited to what is immediately visible
- Evidence of brake fluid contamination
- Anti-lock braking system (ABS) mechanics
- Meters indicating oil and fuel consumption or the degree of oil and fuel consumption
- Reason for oil leaks
- Oil pump strainer to assess sludge build up
- Wheel cylinders
- Vehicle electrics and electronics
- Transmission mechanics
- Engine cylinder compression
- Engine mountings
- Water pump/fan
- Body water leaks or reason for leaks
- Odometer and camshaft belt, drive belt and timing belt
- Estimated expiry of exhaust system, clutch, dual mass flywheels
- Standard to which repairs or service history have been completed
- Functionality of audio-visual or entertainment system including CD, Cassette, TV, DVD, iPod connectivity, sensors, alarm/security devices, satellite navigation systems/GPS
- Degree of gas emissions
- Catalytic converters
- Additional accessories included as a result of owner's modifications
- Mechanical switching of wipers and lights
- LPG systems
- Air conditioning efficiency
- Status of habitation areas of motorhomes or caravans
- Vehicle's computer systems, such as trip meter computers, cruise control and any other computer systems
- Technical systems

Disclaimer

- (a) This report is not a warranty.
- (b) The scope of this inspection is visual only and limited to the items checked in the body of the report on the date of inspection, reflecting the age of the vehicle and kilometres travelled on that date. As the inspection is visual only, it does not involve the removal of any parts or components and is therefore limited in scope.
- (c) It is the responsibility of the buyer to check and diligence the vehicle at time of purchase.
- (d) RedBook Inspect assumes no liability or warranty for any defects that may arise subsequent to the date of inspection.
- (e) This report must not be sold or provided to any third party, except with RedBook Inspect's prior written consent.