

Vehicle Description

DATE INSPECTED: 22/07/2020

145799 Renault Master X62 Cab Chassis MWB 2dr AMT 6sp 2.3DT

VIN	VF1VDU9F3D0684671
Compliance Date	04/2014
Build Date	2013
Odometer Reading	119852
Registration Number	1SC2UV
Registration Expiry	02/06/2021
Last Serviced	See Dealer





Overall Rating

Note: 5 Star ratings are usually reserved to near new and ex-factory driven demonstrator vehicles

★★★★☆☆ 3.5 - GOOD	Seats	4.0 - GOOD	Suspension
5.0 - VERY GOOD	Lights	★★★★☆ 4.0 - GOOD	Brakes
4.0 - GOOD	Engine	4.0 - GOOD	Body & Paint
4.0 - GOOD	Mountings	4.0 - GOOD	Tyres
★★★★ ☆ 4.0 - GOOD	Transmission / Gearbox	5.0 - VERY GOOD	Road Test
★★★★☆ 4.0 - GOOD	Steering	NA NOTAPPLICABLE	Other

★★★☆☆	Seats General wear to seats and trims, in good condition for age/kilometres travelled with commercial use.
****	Lights Lights and lenses in good condition and all operational at time of inspection.
****	Engine Engine/engine bay in good condition at time of inspection, reflecting kilometres and age. No diagnostic fault codes found at time of inspection.
★★★★☆	Mountings Mountings are in good condition for age and kilometres.
★★★★☆	Transmission / Gearbox Transmission operating well at time of inspection to be expected with kilometres.
****	Steering Steering components present in well-maintained condition reflecting age and the kilometres on vehicle.
	☑ INFO@REDBOOKINSPECT.COM.AU ☑ WWW.REDBOOKINSPECT.COM.AU PAGE 2 OF

	NSPECT DEALER INSPECTION REPORT *DEALER USE ONLY - This report does not constitute a full pre-purchase inspection
★★★★ ☆	Suspension All visible suspension and suspension bushes in good condition reflecting kilometres and age.
****	Brakes Brake pads and discs are in good condition, general wear showing to be expected.
****	Body & Paint Body and paint in good condition with very minimal superficial imperfections to be expected with age and kilometres travelled with commercial usage
****	Tyres Very minimal wear to tyres
****	Road Test Vehicle drove and performed well on road test.
ΝΑ	Other
6 1300 373 992	INFO@REDBOOKINSPECT.COM.AU

DEALER INSPECTION REPORT *DEALER USE ONLY - This report does not constitute a full pre-purchase inspection

 $\underbrace{\mathsf{Overall}}_{\bigstar\bigstar\bigstar\bigstar\bigstar\bigstar} \underbrace{\mathsf{Corr}}_{\bigstar} \underbrace{\mathsf{Corr}}_{\bullet} \underbrace{\mathsf{Corr}}_{\bullet} \underbrace{\mathsf{Corr}}_{\bullet} \underbrace{\mathsf{Corr}}_{\bullet} \underbrace{\mathsf{Corr}}_{\bullet} \underbrace{\mathsf{Corr}}$












General Comments

Overall this vehicle has been rated as '4 STARS' taking into consideration age, kilometres travelled and vehicle use. Vehicle presents in a well maintained condition. Note: all accessories may not have been accessible or tested at time of inspection. Possible minor inclusions and imperfections to be expected with a vehicle of these kilometres, commercial use and age


















💪 1300 373 992

PAGE 9 OF 12











Item Ratings

★★★★★ 5.0 ★★★★ ★ 4.5	VERY GOOD Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age & kms of vehicle.
★★★★☆ 4.0 ★★★☆☆ 3.5	GOOD
★★★☆☆ 3.0 ★★☆☆☆ 2.5	FAIR Item found to be in working order with some signs of damage and/or wear & tear, consistent with age & kms of vehicle.
★★☆☆☆ 2.0★☆☆☆☆ 1.5	POOR
★☆☆☆☆ 1.0 ★☆☆☆☆ 0.5	VERY POOR Item found not to be in working order and/or major signs of damage and/or wear & tear.
NA	NOT APPLICABLE Vehicle does not have this item fitted/installed.
NC	NOT CHECKED Potential defect observed but item not further investigated/dismantled.

RedBook Inspect does not check the following items

- Brake function and lining material, brake drums, limited to what is immediately visible
- Evidence of brake fluid contamination
- Anti-lock braking system (ABS) mechanics
- Meters indicating oil and fuel consumption or the degree of oil and fuel consumption
- Reason for oil leaks
- Oil pump strainer to assess sludge build up
- Wheel cylinders
- Vehicle electrics and electronics
- Transmission mechanics
- Engine cylinder compression
- Engine mountings
- Water pump/fan
- Body water leaks or reason for leaks

- Odometer and camshaft belt, drive belt and timing belt
- Estimated expiry of exhaust system, clutch, dual mass flywheels
- Standard to which repairs or service history have been completed
- Functionality of audio-visual or entertainment system including CD, Cassette, TV, DVD, iPod connectivity, sensors, alarm/security devices, satellite navigation systems/GPS
- Degree of gas emissions
- Catalytic converters
- Additional accessories included as a result of owner's modifications
- Mechanical switching of wipers and lights
- LPG systems
- Air conditioning efficiency
- Status of habitation areas of motorhomes or caravans
- Vehicle's computer systems, such as trip meter computers, cruise control and any other computer systems
- Technical systems

Disclaimer

- (a) This report is not a warranty.
- (b) The scope of this inspection is visual only and limited to the items checked in the body of the report on the date of inspection, reflecting the age of the vehicle and kilometres travelled on that date. As the inspection is visual only, it does not involve the removal of any parts or components and is therefore limited in scope.
- (C) It is the responsibility of the buyer to check and diligence the vehicle at time of purchase.
- (d) RedBook Inspect assumes no liability or warranty for any defects that may arise subsequent to the date of inspection.
- (e) This report must not be sold or provided to any third party, except with RedBook Inspect's prior written consent.

\[
 \ldots 1300 373 992
 \]

INFO@REDBOOKINSPECT.COM.AU

PAGE 12 OF 12