

Vehicle Description

DATE INSPECTED: 12/11/2020

2017 Ford Ranger Hi Rider MK2 XL 2.2LT Turbo Diesel Automatic STOCK#146339

VIN MNAUMAF80GW670748
 Compliance Date 12/2016
 Build Date 2016
 Odometer Reading 24523
 Registration Number 1KD3LI
 Registration Expiry 15/04/2021
 Last Serviced 17/1/2020



Overall Rating

Note: 5 Star ratings are usually reserved to near new and ex-factory driven demonstrator vehicles



Seats

4.0 - GOOD



Suspension

4.0 - GOOD



Lights

5.0 - VERY GOOD



Brakes

4.0 - GOOD



Engine

4.0 - GOOD



Body & Paint

4.0 - GOOD



Mountings

4.0 - GOOD



Tyres

4.0 - GOOD



Transmission / Gearbox

4.0 - GOOD



Road Test

4.0 - GOOD



Steering

4.0 - GOOD



Other

4.0 - GOOD

**Seats**

Very minimal wear to seats and trims, in good condition for age and kilometres travelled with commercial type use

**Lights**

All lights and lamps are operational and in good condition, free of cracks or moisture at time of inspection

**Engine**

Engine/engine bay is in very good/well maintained condition at time of inspection. No diagnostic fault codes found at time of inspection.

**Mountings**

Visible mounts are in good condition to be expected with kilometres and age.

**Transmission / Gearbox**

Transmission selecting gears correctly and smoothly at time of inspection

**Steering**

Steering turning lock to lock smoothly at time of inspection. All visible steering components in good condition to be expected with kilometres and age. Steering components present in well-maintained condition reflecting age and the kilometres on vehicle. All steering components presenting in good condition.



Suspension

All visible suspension and suspension bushes in good condition reflecting kilometres and age.



Brakes

Front and rear brakes wearing consistent with age and kilometres of the vehicle



Body & Paint

Body and paint in good condition with very minimal superficial imperfections to be expected with age and kilometres travelled with commercial use



Tyres

Front tyres approximately 7mm tread depth Rear tyres approximately 7mm tread depth Wheels are in good condition, free of gutter rash



Road Test

Vehicle performed well on road test



Other

NOTE - Not all accessories and extras have been tested at time of inspection

Overall




General Comments

Overall this vehicle has been rated as '4 STARS' taking into consideration age and kilometres travelled. Vehicle presents in a well maintained condition. Possible minor inclusions and imperfections to be expected with a vehicle of these kilometres and age which is used for commercial use

*DEALER USE ONLY - This report does not constitute a full pre-purchase inspection
















Item Ratings

★★★★★ 5.0 **VERY GOOD**

★★★★☆ 4.5 Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age & kms of vehicle.

★★★★☆ 4.0 **GOOD**

★★★☆☆ 3.5

★★★☆☆ 3.0 **FAIR**

★★★☆☆ 2.5 Item found to be in working order with some signs of damage and/or wear & tear, consistent with age & kms of vehicle.

★★☆☆☆ 2.0 **POOR**

★☆☆☆☆ 1.5

★☆☆☆☆ 1.0 **VERY POOR**

★☆☆☆☆ 0.5 Item found not to be in working order and/or major signs of damage and/or wear & tear.

NA NOT APPLICABLE

Vehicle does not have this item fitted/installed.

NC NOT CHECKED

Potential defect observed but item not further investigated/dismantled.

RedBook Inspect does not check the following items

- Brake function and lining material, brake drums, limited to what is immediately visible
- Evidence of brake fluid contamination
- Anti-lock braking system (ABS) mechanics
- Meters indicating oil and fuel consumption or the degree of oil and fuel consumption
- Reason for oil leaks
- Oil pump strainer to assess sludge build up
- Wheel cylinders
- Vehicle electrics and electronics
- Transmission mechanics
- Engine cylinder compression
- Engine mountings
- Water pump/fan
- Body water leaks or reason for leaks
- Odometer and camshaft belt, drive belt and timing belt
- Estimated expiry of exhaust system, clutch, dual mass flywheels
- Standard to which repairs or service history have been completed
- Functionality of audio-visual or entertainment system including CD, Cassette, TV, DVD, iPod connectivity, sensors, alarm/security devices, satellite navigation systems/GPS
- Degree of gas emissions
- Catalytic converters
- Additional accessories included as a result of owner's modifications
- Mechanical switching of wipers and lights
- LPG systems
- Air conditioning efficiency
- Status of habitation areas of motorhomes or caravans
- Vehicle's computer systems, such as trip meter computers, cruise control and any other computer systems
- Technical systems

Disclaimer

- (a) This report is not a warranty.
- (b) The scope of this inspection is visual only and limited to the items checked in the body of the report on the date of inspection, reflecting the age of the vehicle and kilometres travelled on that date. As the inspection is visual only, it does not involve the removal of any parts or components and is therefore limited in scope.
- (c) It is the responsibility of the buyer to check and diligence the vehicle at time of purchase.
- (d) RedBook Inspect assumes no liability or warranty for any defects that may arise subsequent to the date of inspection.
- (e) This report must not be sold or provided to any third party, except with RedBook Inspect's prior written consent.