

**Vehicle Description**

DATE INSPECTED: 12/11/2020

Mercedes Benz Sprinter 2.1LT Turbo Diesel Automatic STOCK# 146380

VIN WDB9066332P199011  
Compliance Date 6/2016  
Build Date Not located  
Odometer Reading 144945  
Registration Number N/A  
Registration Expiry  
Last Serviced 5/11/2020



**Overall Rating**

Note: 5 Star ratings are usually reserved to near new and ex-factory driven demonstrator vehicles



4.0 - GOOD

Seats



4.0 - GOOD

Suspension



5.0 - VERY GOOD

Lights



4.0 - GOOD

Brakes



4.0 - GOOD

Engine



4.0 - GOOD

Body & Paint



4.0 - GOOD

Mountings



4.0 - GOOD

Tyres



4.0 - GOOD

Transmission / Gearbox



4.0 - GOOD

Road Test



4.0 - GOOD

Steering



4.0 - GOOD

Other



**Seats**

Seats and trims in good condition for age and kilometres travelled, with commercial type use

---



**Lights**

All lights and lamps are operational and in good condition, free of cracks or moisture at time of inspection

---



**Engine**

Engine/engine bay is in very good/well maintained condition at time of inspection. No diagnostic fault codes found at time of inspection.

---



**Mountings**

Visible mounts are in good condition to be expected with kilometres and age.

---



**Transmission / Gearbox**

Transmission selecting gears correctly and smoothly at time of inspection

---



**Steering**

Steering turning lock to lock smoothly at time of inspection. All visible steering components in good condition to be expected with kilometres and age.

---



**Suspension**

All visible suspension and suspension bushes in good condition reflecting kilometres and age.

---



**Brakes**

Front and rear brake pads wearing consistent with age and kilometres Front and rear disc rotors wearing consistent with age and kilometres of the vehicle

---



**Body & Paint**

Body and paint in good condition with very minimal superficial imperfections to be expected with age and kilometres travelled with commercial use

---



**Tyres**

Front tyres approximately 6mm tread depth Rear tyres approximately 6mm tread depth Wheels are in good condition, free of gutter rash

---



**Road Test**

Vehicle performed well on road test

---



**Other**

NOTE - Not all accessories and extras have been tested at time of inspection

---


Overall




General Comments

Overall this vehicle has been rated as '4 STARS' taking into consideration age and kilometres travelled. Vehicle presents in a well maintained condition. Possible minor inclusions and imperfections to be expected with a vehicle of these kilometres and age which is used for commercial use

















24 Oil service plus/maintenance service/additional maintenance work		25 Oil service plus/maintenance service/additional maintenance work	
Date	5/11/20	Date	
Odometer reading	144,932	Odometer reading	
Order no.		Order no.	
Remaining time		Remaining time	
Remaining distance		Remaining distance	
<b>Work in addition to the maintenance service</b> <input type="checkbox"/> Z <input type="checkbox"/> Z1 <input type="checkbox"/> Z3 <input type="checkbox"/> ZA <input type="checkbox"/> ZL <input type="checkbox"/> J2 <input type="checkbox"/> J4 <input type="checkbox"/> J10 <input type="checkbox"/> J15		<b>Work in addition to the maintenance service</b> <input type="checkbox"/> Z <input type="checkbox"/> Z1 <input type="checkbox"/> Z3 <input type="checkbox"/> ZA <input type="checkbox"/> ZL <input type="checkbox"/> J2 <input type="checkbox"/> J4 <input type="checkbox"/> J10 <input type="checkbox"/> J15	
<b>Oil change</b> Sheet No./viscosity _____ Engine _____ Manual transmission _____ Automatic transmission _____ Transfer case _____ Front axle _____ Rear axle _____		<b>Oil change</b> Sheet No./viscosity _____ Engine _____ Manual transmission _____ Automatic transmission _____ Transfer case _____ Front axle _____ Rear axle _____	
<b>Service carried out in accordance with Daimler AG specifications:</b> Yes/No _____		<b>Service carried out in accordance with Daimler AG specifications:</b> Yes/No _____	
<b>Extended until next service</b> Mercedes-Benz Mobilo/MobiloVan <sup>1</sup> Yes/No _____		<b>Extended until next service</b> Mercedes-Benz Mobilo/MobiloVan <sup>1</sup> Yes/No _____	
<b>Warranty against perforation through corrosion</b> Yes/No _____ <small>1 Only in certain countries.</small>		<b>Warranty against perforation through corrosion</b> Yes/No _____ <small>1 Only in certain countries.</small>	
<b>Replaced:</b> <input type="checkbox"/> Air filter element <input type="checkbox"/> Dust filter: heating/ventilation <input type="checkbox"/> Combination filter <input type="checkbox"/> Fuel filter <input type="checkbox"/> Coolant <input type="checkbox"/> Brake fluid <input type="checkbox"/> Spark plugs <input type="checkbox"/> Front axle brake pads/linings		<b>Replaced:</b> <input type="checkbox"/> Air filter element <input type="checkbox"/> Dust filter: heating/ventilation <input type="checkbox"/> Combination filter <input type="checkbox"/> Fuel filter <input type="checkbox"/> Coolant <input type="checkbox"/> Brake fluid <input type="checkbox"/> Spark plugs <input type="checkbox"/> Front axle brake pads/linings	
<b>IAN ROSE MOTORS</b> 13 Nellbern Road MOORABBIN 3189 Tel: 03 9555 9291 <small>Signature/Stamp of Mercedes-Benz Service Centre</small>			

**Item Ratings**

★★★★★ 5.0 **VERY GOOD**

★★★★☆ 4.5 Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age & kms of vehicle.

★★★★☆ 4.0 **GOOD**

★★★☆☆ 3.5

★★★☆☆ 3.0 **FAIR**

★★★☆☆ 2.5 Item found to be in working order with some signs of damage and/or wear & tear, consistent with age & kms of vehicle.

★★☆☆☆ 2.0 **POOR**

★★☆☆☆ 1.5

★☆☆☆☆ 1.0 **VERY POOR**

★☆☆☆☆ 0.5 Item found not to be in working order and/or major signs of damage and/or wear & tear.

**NA NOT APPLICABLE**

Vehicle does not have this item fitted/installed.

**NC NOT CHECKED**

Potential defect observed but item not further investigated/dismantled.

**RedBook Inspect does not check the following items**

- Brake function and lining material, brake drums, limited to what is immediately visible
- Evidence of brake fluid contamination
- Anti-lock braking system (ABS) mechanics
- Meters indicating oil and fuel consumption or the degree of oil and fuel consumption
- Reason for oil leaks
- Oil pump strainer to assess sludge build up
- Wheel cylinders
- Vehicle electrics and electronics
- Transmission mechanics
- Engine cylinder compression
- Engine mountings
- Water pump/fan
- Body water leaks or reason for leaks
- Odometer and camshaft belt, drive belt and timing belt
- Estimated expiry of exhaust system, clutch, dual mass flywheels
- Standard to which repairs or service history have been completed
- Functionality of audio-visual or entertainment system including CD, Cassette, TV, DVD, iPod connectivity, sensors, alarm/security devices, satellite navigation systems/GPS
- Degree of gas emissions
- Catalytic converters
- Additional accessories included as a result of owner's modifications
- Mechanical switching of wipers and lights
- LPG systems
- Air conditioning efficiency
- Status of habitation areas of motorhomes or caravans
- Vehicle's computer systems, such as trip meter computers, cruise control and any other computer systems
- Technical systems

**Disclaimer**

- (a) This report is not a warranty.
- (b) The scope of this inspection is visual only and limited to the items checked in the body of the report on the date of inspection, reflecting the age of the vehicle and kilometres travelled on that date. As the inspection is visual only, it does not involve the removal of any parts or components and is therefore limited in scope.
- (c) It is the responsibility of the buyer to check and diligence the vehicle at time of purchase.
- (d) RedBook Inspect assumes no liability or warranty for any defects that may arise subsequent to the date of inspection.
- (e) This report must not be sold or provided to any third party, except with RedBook Inspect's prior written consent.