

Vehicle Description

DATE INSPECTED: 27/01/2021

Toyota hilux

VIN Mroju3cdx00001280
 Compliance Date 7/17
 Build Date July 17
 Odometer Reading 86657
 Registration Number Unregistered
 Registration Expiry
 Last Serviced Refer to dealer.



Overall Rating

Note: 5 Star ratings are usually reserved to near new and ex-factory driven demonstrator vehicles



Seats



Lights



Engine



Mountings



Transmission / Gearbox



Steering



Suspension



Brakes



Body & Paint



Tyres



Road Test



Other



Seats

All cloth seats are ok at time of inspection



Lights

Lights and lenses in good condition and all operational at time of inspection



Engine

Engine/engine bay in good condition at time of inspection, reflecting kilometres and age No diagnostic fault codes found at time of inspection refer to photo attached



Mountings

Visible mounts are in good condition to be expected with kilometres and age



Transmission / Gearbox

Transmission operating well at time of inspection to be expected with kilometres



Steering

All steering components are in good condition to be expected with kilometres and age



Suspension

All visible steering components in good condition reflecting age and kilometres



Brakes

All brake pads are wearing consistent with age and kilometres traveled All brake discs are ok at time of inspection



Body & Paint

Body and paint presenting in good condition. Very minor marks and scratches to various panels of vehicle to be expected with age and kilometres traveled



Tyres

All tyres are wearing consistent with age and kilometres traveled



Road Test

Vehicle drove well and performed well on road test




Other

Overall




General Comments

Overall this vehicle has been rated as "4 Star" taken into consideration age, kilometres traveled and vehicle use. Vehicle presents in a well maintained condition.















Item Ratings

★★★★★ 5.0 VERY GOOD

★★★★★ 4.5 Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age & kms of vehicle.

★★★★☆ 4.0 GOOD

★★★★☆ 3.5

★★★☆☆ 3.0 FAIR

★★★☆☆ 2.5 Item found to be in working order with some signs of damage and/or wear & tear, consistent with age & kms of vehicle.

★★☆☆☆ 2.0 POOR

★★☆☆☆ 1.5

★☆☆☆☆ 1.0 VERY POOR

★☆☆☆☆ 0.5 Item found not to be in working order and/or major signs of damage and/or wear & tear.

NA NOT APPLICABLE

Vehicle does not have this item fitted/installed.

NC NOT CHECKED

Potential defect observed but item not further investigated/dismantled.

RedBook Inspect does not check the following items

- Brake function and lining material, brake drums, limited to what is immediately visible
- Evidence of brake fluid contamination
- Anti-lock braking system (ABS) mechanics
- Meters indicating oil and fuel consumption or the degree of oil and fuel consumption
- Reason for oil leaks
- Oil pump strainer to assess sludge build up
- Wheel cylinders
- Vehicle electrics and electronics
- Transmission mechanics
- Engine cylinder compression
- Engine mountings
- Water pump/fan
- Body water leaks or reason for leaks
- Odometer and camshaft belt, drive belt and timing belt
- Estimated expiry of exhaust system, clutch, dual mass flywheels
- Standard to which repairs or service history have been completed
- Functionality of audio-visual or entertainment system including CD, Cassette, TV, DVD, iPod connectivity, sensors, alarm/security devices, satellite navigation systems/GPS
- Degree of gas emissions
- Catalytic converters
- Additional accessories included as a result of owner's modifications
- Mechanical switching of wipers and lights
- LPG systems
- Air conditioning efficiency
- Status of habitation areas of motorhomes or caravans
- Vehicle's computer systems, such as trip meter computers, cruise control and any other computer systems
- Technical systems

Disclaimer

- (a) This report is not a warranty.
- (b) The scope of this inspection is visual only and limited to the items checked in the body of the report on the date of inspection, reflecting the age of the vehicle and kilometres travelled on that date. As the inspection is visual only, it does not involve the removal of any parts or components and is therefore limited in scope.
- (c) It is the responsibility of the buyer to check and diligence the vehicle at time of purchase.
- (d) RedBook Inspect assumes no liability or warranty for any defects that may arise subsequent to the date of inspection.
- (e) This report must not be sold or provided to any third party, except with RedBook Inspect's prior written consent.