

Vehicle Description

Holden Colorado

DATE INSPECTED: 27/01/2021

VIN	Mmu148dkogh642882
Compliance Date	4/16
Build Date	March 16
Odometer Reading	70226
Registration Number	Unregistered
Registration Expiry	
Last Serviced	Refer to dealer.



Overall Rating

Note: 5 Star ratings are usually reserved to near new and ex-factory driven demonstrator vehicles

★★★★★☆
4.0 - GOOD

Seats

★★★★★☆
4.0 - GOOD

Suspension

★★★★★☆
4.0 - GOOD

Lights

★★★★★☆
4.0 - GOOD

Brakes

★★★★★☆
4.0 - GOOD

Engine

★★★★★☆
4.0 - GOOD

Body & Paint

★★★★★☆
4.0 - GOOD

Mountings

★★★★★☆
4.0 - GOOD

Tyres

★★★★★☆
4.0 - GOOD

Transmission / Gearbox

★★★★★☆
4.0 - GOOD

Road Test

★★★★★☆
4.0 - GOOD

Steering

★★★★★☆
5.0 - VERY GOOD

Other

**Seats**

All cloth seats are ok at time of inspection

**Lights**

Lights and lenses in good condition and all operational at time of inspection

**Engine**

Engine/engine bay in good condition at time of inspection, reflecting kilometres and age No diagnostic fault codes found at time of inspection refer to photo attached

**Mountings**

Visible mounts are in good condition to be expected with kilometres and age

**Transmission / Gearbox**

Transmission operating well at time of inspection to be expected with kilometres

**Steering**

All steering components are in good condition to be expected with kilometres and age



**Suspension**

All visible steering components in good condition reflecting age and kilometres

**Brakes**

All brake pads are wearing consistent with age and kilometres traveled All brake discs are ok at time of inspection

**Body & Paint**

Body and paint presenting in good condition. Very minor marks and scratches to various panels of vehicle to be expected with age and kilometres traveled

**Tyres**

All tyres are wearing consistent with age and kilometres traveled

**Road Test**

Vehicle drove well and performed well on road test


**Other**

Overall**General Comments**

Overall this vehicle has been rated as "4 Star" taking into consideration age, kilometres traveled and vehicle use. Vehicle presents in a well maintained condition.



Red Book
INSPECT




Red Book
INSPECT



INSPECT



INSPECT





RedBook
INSPECT




RedBook
INSPECT





Red Book
INSPECT



Red Book
INSPECT



Red Book
INSPECT

Item Ratings

★★★★★ 5.0 **VERY GOOD**

Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age & kms of vehicle.

★★★★☆ 4.0 **GOOD****★★★★☆** 3.5**★★★★☆** 3.0 **FAIR**

Item found to be in working order with some signs of damage and/or wear & tear, consistent with age & kms of vehicle.

★★★★☆ 2.0 **POOR****★★★★☆** 1.5**★★★★☆** 1.0 **VERY POOR**

Item found not to be in working order and/or major signs of damage and/or wear & tear.

NA **NOT APPLICABLE**

Vehicle does not have this item fitted/installed.

NC **NOT CHECKED**

Potential defect observed but item not further investigated/dismantled.

RedBook Inspect does not check the following items

- Brake function and lining material, brake drums, limited to what is immediately visible
- Evidence of brake fluid contamination
- Anti-lock braking system (ABS) mechanics
- Meters indicating oil and fuel consumption or the degree of oil and fuel consumption
- Reason for oil leaks
- Oil pump strainer to assess sludge build up
- Wheel cylinders
- Vehicle electrics and electronics
- Transmission mechanics
- Engine cylinder compression
- Engine mountings
- Water pump/fan
- Body water leaks or reason for leaks
- Odometer and camshaft belt, drive belt and timing belt
- Estimated expiry of exhaust system, clutch, dual mass flywheels
- Standard to which repairs or service history have been completed
- Functionality of audio-visual or entertainment system including CD, Cassette, TV, DVD, iPod connectivity, sensors, alarm/security devices, satellite navigation systems/GPS
- Degree of gas emissions
- Catalytic converters
- Additional accessories included as a result of owner's modifications
- Mechanical switching of wipers and lights
- LPG systems
- Air conditioning efficiency
- Status of habitation areas of motorhomes or caravans
- Vehicle's computer systems, such as trip meter computers, cruise control and any other computer systems
- Technical systems

Disclaimer

- (a) This report is not a warranty.
- (b) The scope of this inspection is visual only and limited to the items checked in the body of the report on the date of inspection, reflecting the age of the vehicle and kilometres travelled on that date. As the inspection is visual only, it does not involve the removal of any parts or components and is therefore limited in scope.
- (c) It is the responsibility of the buyer to check and diligence the vehicle at time of purchase.
- (d) RedBook Inspect assumes no liability or warranty for any defects that may arise subsequent to the date of inspection.
- (e) This report must not be sold or provided to any third party, except with RedBook Inspect's prior written consent.