

Vehicle Description

DATE INSPECTED: 21/04/2021

Hyundai iload Diesel Van

VIN KMFWBX7KMFU684108

Compliance Date 11/14

Build Date 10/14

Odometer Reading 182705

Registration Number Unregistered

Registration Expiry

Last Serviced



Overall Rating

Note: 5 Star ratings are usually reserved to near new and ex-factory driven demonstrator vehicles



Seats

4.0 - GOOD



Suspension

4.0 - GOOD



Lights

4.0 - GOOD



Brakes

4.0 - GOOD



Engine

4.0 - GOOD



Body & Paint

4.0 - GOOD



Mountings

4.0 - GOOD



Tyres

4.0 - GOOD



Transmission / Gearbox

4.0 - GOOD



Road Test

4.0 - GOOD



Steering

4.0 - GOOD



Other

4.0 - GOOD



**Seats**

All seats are ok at time of inspection



**Lights**

Lights and lenses in good condition and all operational at time of inspection



**Engine**

Engine/engine bay in good condition at time of inspection, reflective Kim's and ages. No diagnostic faults codes at time of inspection, refer photos attached



**Mountings**

Visible mounts are in good condition to be expected with Klms and age.



**Transmission / Gearbox**

Transmission presents in a good condition for age and kilometres.



**Steering**

All visible steering components are in good condition reflecting age and kilometres travelled.



**Suspension**

All Visible suspension and suspension bushes presents well for age and kilometres travelled.

---



**Brakes**

Brake pads and disc presents well, wearing consistent with age and kilometres travelled.

---



**Body & Paint**

Bodywork and paint presents well minimal superficial marks

---



**Tyres**

Tyres are in good condition, consistent with age and kilometres travelled.

---



**Road Test**

Vehicle performed well on road test.

---



**Other**

---

Overall




General Comments

Overall this vehicle has been rated a 4 star taking into consideration ages and klms travelled. Vehicle presents in a well maintained condition.











\*DEALER USE ONLY - This report does not constitute a full pre-purchase inspection







## Item Ratings

★★★★★ 5.0 **VERY GOOD**

★★★★☆ 4.5 Item found to be in working order and/or no obvious signs of damage/degradation, consistent with age & kms of vehicle.

★★★★☆ 4.0 **GOOD**

★★★☆☆ 3.5

★★★☆☆ 3.0 **FAIR**

★★★☆☆ 2.5 Item found to be in working order with some signs of damage and/or wear & tear, consistent with age & kms of vehicle.

★★☆☆☆ 2.0 **POOR**

★★☆☆☆ 1.5

★☆☆☆☆ 1.0 **VERY POOR**

★☆☆☆☆ 0.5 Item found not to be in working order and/or major signs of damage and/or wear & tear.

**NA NOT APPLICABLE**

Vehicle does not have this item fitted/installed.

**NC NOT CHECKED**

Potential defect observed but item not further investigated/dismantled.

## RedBook Inspect does not check the following items

- Brake function and lining material, brake drums, limited to what is immediately visible
- Evidence of brake fluid contamination
- Anti-lock braking system (ABS) mechanics
- Meters indicating oil and fuel consumption or the degree of oil and fuel consumption
- Reason for oil leaks
- Oil pump strainer to assess sludge build up
- Wheel cylinders
- Vehicle electrics and electronics
- Transmission mechanics
- Engine cylinder compression
- Engine mountings
- Water pump/fan
- Body water leaks or reason for leaks
- Odometer and camshaft belt, drive belt and timing belt
- Estimated expiry of exhaust system, clutch, dual mass flywheels
- Standard to which repairs or service history have been completed
- Functionality of audio-visual or entertainment system including CD, Cassette, TV, DVD, iPod connectivity, sensors, alarm/security devices, satellite navigation systems/GPS
- Degree of gas emissions
- Catalytic converters
- Additional accessories included as a result of owner's modifications
- Mechanical switching of wipers and lights
- LPG systems
- Air conditioning efficiency
- Status of habitation areas of motorhomes or caravans
- Vehicle's computer systems, such as trip meter computers, cruise control and any other computer systems
- Technical systems

## Disclaimer

- (a) This report is not a warranty.
- (b) The scope of this inspection is visual only and limited to the items checked in the body of the report on the date of inspection, reflecting the age of the vehicle and kilometres travelled on that date. As the inspection is visual only, it does not involve the removal of any parts or components and is therefore limited in scope.
- (c) It is the responsibility of the buyer to check and diligence the vehicle at time of purchase.
- (d) RedBook Inspect assumes no liability or warranty for any defects that may arise subsequent to the date of inspection.
- (e) This report must not be sold or provided to any third party, except with RedBook Inspect's prior written consent.